
Installation Guide

Cobra Spectrum




WARNING: Risk of electrical shock. Please read these instructions completely and carefully. Disconnect power before servicing or installing product.


1 Cut LED strip to required size, taking care to only cut at intervals marked on the product. Note the maximum series length to avoid voltage drop.



3 Solder connecting 'wire tails' to terminals for connection to power supply, or for 'bridging wires' for linking of strip segments. Always ensure positive-positive and negative-negative connection.



2 Ensure that your channel letter or application area is clean and free of debris. Remove adhesive liner from the back of strip and press flex strip into place.



4 Connect to RGB controller and power supply to test.

